


Photograph 2: Typical streetscape within the 1954 section of Haines Acres. Note the uniform setback, the predominance of ranch houses, and the lack of sidewalks. View facing north up Erlen Drive (December 2007).



Photograph 3: Typical streetscape within the 1955 section of Haines Acres. Note the sidewalks, typical split-level houses, and lack of streetscaping. View facing north up Sundale Road (December 2007).



Photograph 4: Typical streetscape along Eastwood Drive, which runs through the 1955 section of Haines Acres into the 1957 section. Note the rolling topography and banked siting of the ranch houses. View facing east (December 2007).



Photograph 5: Typical streetscape within the 1960 section of Haines Acres. Note the curvilinear streets and increasing variety of split-level homes. View facing northwest up Brighton Drive (December 2007).



Photograph 6: Typical streetscape within the 1962 section of Haines Acres. Note the curvilinear streets and rolling topography, as well as the similarity between this streetscape and those of earlier sections. View facing northeast up Hartford Road (December 2007).




Photograph 7: Typical streetscape within the 1966 section of Haines Acres. Note the addition of bay windows and two-car garages to the split-level house. View facing south down Cortleigh Drive (December 2007).



Photograph 8: Typical streetscape within the 1967 section of Haines Acres. This small section of the subdivision is similar to the earlier portions, with predominantly split-level houses, a rolling topography, and curvilinear streets. View facing northeast up Forrest Lane (December 2007).



Photograph 9: Typical streetscape within the 1968 section of Haines Acres. Located near the 1954 tracts, this section mostly consists of a variation of the 1950s ranch houses. These 1960s dwellings have U-shaped floor plans with central porches. View facing northwest up Hunting Park Lane (December 2007).



Photograph 10: Typical streetscape within the 1973 section of Haines Acres. Note the difference in layout of the houses on the lots and the increased variation in house designs from earlier sections. View facing east along Round Hill Road (December 2007).




Photograph 11: Typical dwelling on a corner lot, placed facing the corner rather than the cross streets. This house placement is used on almost every corner lot in Haines Acres. View facing northeast from the corner of Crystal Lane and Cambridge Road (December 2007).



Photograph 12: The house at 541 Sundale Road was built when the property on which Haines Acres is located was used as a farm. The dwelling was integrated into the subdivision when the other farm buildings were demolished in the 1970s. View facing northeast from Sundale Road (December 2007).



Photograph 13: 2469 Wharton Road, located in the 1955 section. Typical one-story ranch house with carport, original windows, and a projecting hipped-roof ell with integral entry porch. View facing north (December 2007).



Photograph 14: Typical ranch houses along Auburn Road in the 1957 section. Note the rectangular footprints, low-pitched side gable or hipped roofs, and attached garages. View facing northwest (December 2007).




Photograph 15: 2980 Chesapeake Road, located in the 1966 section. Typical ranch house with an L-shaped footprint and two-car garage. View facing southwest (December 2007).



Photograph 16: 2601 Durham Road, located in the 1960 section. Typical ranch house with a U-shaped footprint and a one-car garage. Note the picture window in the center of the facade, a typical variation of ranch houses throughout the development. View facing northeast (December 2007).



Photograph 17: 2450 Wharton Road, located in the 1955 section. Typical banked ranch house with the garage level exposed to the front. Note the location of the entrance in a recessed corner, which is a typical variation of ranch houses in Haines Acres. View facing south (December 2007).



Photograph 18: 2451 Wharton Road, located in the 1955 section. Typical banked ranch house, with the exposed basement level to the rear of the house. View facing northeast (December 2007).



Photograph 19: Sunrooms and decks are common additions to the rear elevations of houses in Haines Acres. View facing south from Raleigh Drive in the 1957 section (December 2007).



Photograph 20: Typical ranch houses along Crystal Lane in the 1954 section. Note the enclosed carport on the left, which is a typical alteration on earlier ranch houses. View facing northeast (December 2007).



Photograph 21: 1001 Raleigh Drive. Typical split-level house, found in the 1955 section. Note the hipped roof with side-gable wing design, low-pitched roofline, and original aluminum-framed windows. View facing south (December 2007).



Photograph 22: Additions that alter the original massing and scale of the facade are not common in Haines Acres. When they are constructed, they are predominantly located on rear elevations such as this addition to 2459 Princeton Road in the 1955 section. View facing northwest (December 2007).



Photograph 23: 2524 Stanford Drive, located in the 1957 section. Typical split-level house showing the two-car garage and hipped-roof porch introduced in dwellings constructed from 1957 onward. View facing south (December 2007).



Photograph 24: Dwelling at Berkeley Road and Eastwood Drive in the 1957 section, showing the side-entrance garage, a variation of the typical split-level house in Haines Acres. View facing southeast (December 2007).



Photograph 25: 2632 Eastwood Drive, located in the 1957 section. Typical banked ranch house with the basement level exposed to the front. Note the hipped-roof porch and two-car garage that emerge in the 1957 section of Haines Acres. View facing south (December 2007).



Photograph 26: Dwelling on Milford Lane, showing common features of split-level houses constructed in Haines Acres around 1962. Note the bay window, two-car garage, sidelights, decorative door surround, and the hexagonal stairway window. View facing northwest (December 2007).



Photograph 27: 2431 Wharton Road, in the 1955 section. One of the earlier split-level houses in Haines Acres that has a front gable with a side-gable wing. Also note the picture windows and brick veneer typical throughout the subdivision. View facing northwest (December 2007).



Photograph 28: 2710 Milford Lane. Note the Colonial Revival details that became common in the 1962 section of Haines Acres, such as the portico over the entrance and the sidelights and decorative door surround. View facing south (December 2007).



Photograph 29: 2670 Hartford Road, located in the 1962 section. Typical two-story house with Colonial Revival detail and the original porch. Note the continuation of the low-pitched side-gable roof and attached garage common throughout the subdivision. View facing southeast (December 2007).



Photograph 30: East York Elementary School on Erlen Drive, located within the 1954 section of Haines Acres. The two-story block located at the right side of the photograph is the original building. Wings were constructed to the rear and the north (left) elevations in the late twentieth and early twenty-first centuries. View facing northeast (December 2007).



Photograph 31: Haines Acres Shopping Center, constructed in 1962. The center is located at the corner of Mount Rose Avenue and Haines Road, next to the 1955 section of the subdivision. View facing north (December 2007).



Photograph 32: Signage at the Haines Acres Shopping Center erected ca. 1962. View facing northeast (December 2007).



Photograph 33: Buffer plantings along the Haines Acres Shopping Center boundaries on Raleigh Drive and Erlen Drive. View facing south (December 2007).