


Item 2 of Map Book 4
(12)

SKETCH OF PILING IRON

WESTERN RESERVOIR

FRONT ELEVATION



Holes in Bottom Flange $3/8$ in Sq.
do in Ends of plate $1/2$ " "
do at all other places $1/2$ + 1 in.

10 anchor Bolts - $1/8$ in Sq. - 7 in long. Nut & screw - $3/8$ head stand up } in each range
30 joint do $1/2$ " " $3/2$ " " " " to square head }

4 Ranges wanted

SECTION

